Zyxel

Nebula NR7101 Release Note

Firmware V1.15 Patch 0

Date: August 8, 2022

© Copyright since 1995, Zyxel Communications Corp. All rights

Zyxel Nebula NR7101

V1.15(P0)C0 Release Note

Overview

This document provides firmware release information on Zyxel NR7101, new features and enhancements, bug fix, known issues and workarounds information for Release V1.15 Patch0 C0.

This Firmware is for Nebula NR7101 only (Part Number: NR7101-EUZNN1F), NOT for on premise models.

Model	Part Number	Description
NR7101	NR7101-EU01V1F	5G NR Outdoor Router
Nebula NR7101	NR7101-EUZNN1F	Nebula cloud-managed 5G NR Outdoor Router

Supported Platforms

- Nebula NR7101 V1.15(ACCC.0)C0

New Features and Enhancements

Added Remote Configurator live tool on nebula control center to enable

remotely configuring mobile router via device Web GUI.

Bug fix

1. When IP passthrough client's OUI is a specific string, the client receives a WAN IP address but cannot access the Internet
2. Nuttcp download fails
3. Ethernet links flaps
4. Logging to syslog on module events of "Device in roaming state but not enable the function" case still failed.
5. IP conflict even though there is no device with static IP in the network.

Known Issue

1. DHCPv6 relay function fails

Limitation of Settings:

N/A

Default Setting:

1. Account for GUI:

Username	Password
Admin	Refer to device back label

2. Default URL: http://192.168.1.1 is for the device GUI login