Zyxel

Nebula NR5101 Release Note

Firmware V1.15 Patch 1

Date: November 4, 2022

© Copyright since 1995, Zyxel Communications Corp. All rights

Zyxel Nebula NR5101

V1.15(P1)C0 Release Note

Overview

This document provides firmware release information on Zyxel NR5101, new features and enhancements, bug fix, known issues and workarounds information for Release V1.15 Patch1 C0.

This Firmware is for Nebula Mobile NR5101 only (Part Number: NR5101-EUZNN1F), NOT for on premise models.

Model	Part Number	Description
NR5101	NR5101-EU01V1F	5G NR Indoor Router
Nebula NR5101	NR5101-EUZNN1F	Nebula cloud-managed 5G NR Indoor Router

Supported Platforms

- Nebula NR5101 V1.15(ACCG.1)C0

New Features and Enhancements

N/A

Bug fix

1. [SPR# 220322433] Internet circle add Gateway IP conflict event
2. [SPR# 220614374] download from Nebula ca cert fail
3. [SPR# 220125130] There is no “Nebula” option in 5G route Log category scroll menu and active log in log setting,

Known Issue

N/A

Limitation of Settings:

N/A

Default Setting:

1. Account for GUI:

Username	Password
Admin	Refer to device back label

2. Default URL: http://192.168.1.1 is for the device GUI login